

Chubb Technical Bulletin

Issue No: TB202103

Important Safety Update – Replacement of plated steel fittings for PEFS F3 Subject:

systems

PEFS F3 **Product:**

Hydraulic adaptors and hose couplings used in the discharge system Parts:

In relation to the previously published Technical Bulletin TB20190 issued in December 2019, Chubb was made aware in late October 2021 of a high potential incident whereby the discharge of a PEFS F3 system was obstructed due to rust particles blocking and impairing nozzles.

The PEFS fire system in this case is believed to have been fitted approximately 15 years ago and was converted to a PEFS F3 system in March 2019.

Based on the high potential incident classification, Chubb is now recommending additional actions for any PEFS F3 system that have plated steel hydraulic fittings and hose couplings older than 5 years, and/or systems that were identified on the last maintenance service record as having nozzle impairments due to rust particles.

Alternative hydraulic fittings are now available for use for the PEFS F3 system. The new fittings are a combination of brass and stainless steel. The fittings were introduced to ensure that all the internal surfaces of the discharge and actuation system would be corrosion resistant, thereby reducing the risk of rust particles blocking or impairing to discharge nozzles. More information can be found in TB202101.

In field actions

All new PEFS F3 systems will be supplied without plated steel fittings and we recommend you contact your local Chubb representative to discuss your options for replacing the plated steel fittings in your existing PEFS F3 system at your earliest convenience.

Important Note: Older systems are expected to be more susceptible to blockages or impairments. As such, it is further recommended that they are given priority in any replacement program being considered.

- For systems still using plated steel fittings or waiting to be replaced, Chubb recommends that the "Distribution System - Clear Passage Test detailed on Page 21 of the PEFS F3 Maintenance Manual, be carried out at the 6-monthly service.
 - o Where multiple nozzles are found to be impaired during a discharge, Service technicians should recommend either.
 - increasing the frequency of the routine service,
 - booking in a non-routine service call to replace the plated steel fittings at the earliest opportunity.

Approved: Craig Hafey Page 1 of 2

Product Manager



Chubb Technical Bulletin

Issue No: TB202103

Note: The maintenance of a PEFS's system should carried out according to the relevant Chubb maintenance manual. Manuals, datasheets and bulletins can be downloaded from the Chubb website.

Effective Date: Immediately

Issue Date: November 2021

Approved: Craig Hafey

Product Manager